

Inspection Report

Report No.: XYKB-140510
Supplier : XY-GLOBAL

Inspection Date: 6th Jun, 2014
Inspector: Leo

Inspection only for: PO . XYKB-140510 Item No. XY72YM006	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY72YM006	12000PCS	1% inspection	0pcs	No failure	12000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

																	
1. Packing	2. Product																
																	
3. Product	4 Product																
	<p>XY-GLOBAL 深圳市真朴电子科技有限公司 XY Electronics Technology Co.,Ltd</p> <table border="1"> <tr> <td>Product Name</td> <td>XY72YM006</td> <td>Inspection Date</td> <td>2014.6.6</td> </tr> <tr> <td>Product Qty</td> <td>12000PCS</td> <td>Inspection Qty</td> <td>1200PCS</td> </tr> <tr> <td>Product No.</td> <td>XY72YM006</td> <td>Inspector</td> <td>Leo</td> </tr> <tr> <td>Product Description</td> <td colspan="3">XY72YM006</td> </tr> </table>	Product Name	XY72YM006	Inspection Date	2014.6.6	Product Qty	12000PCS	Inspection Qty	1200PCS	Product No.	XY72YM006	Inspector	Leo	Product Description	XY72YM006		
Product Name	XY72YM006	Inspection Date	2014.6.6														
Product Qty	12000PCS	Inspection Qty	1200PCS														
Product No.	XY72YM006	Inspector	Leo														
Product Description	XY72YM006																
5. Product:	6. Dimensions report:																

Material	ADC12 A380
Process	CNC
Surface	nickle
Tolerance	+/- 0.01
MOQ	100
Lead Time	25-30
Specification	OEM service
ISO	ISO 9001
Accessories	accessories
Certification	Austrial EU
Quality	ISO 9001
Service	OEM