

Inspection Report

Report No.: XYAN-150302-1
 Supplier : XY-GLOBAL

Inspection Date: 1st Apr, 2015
 Inspector: LEO

Inspection only for: PO . XYBA-150302-1 Item No. XY21ZC089	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC089	8000pcs	7% inspection	0pcs	No failure	8000pcs

Appearance Inspection :
 No failure,

Dimension Inspection:
 No failure , below measurement report for reference.

Assembly Test:
 No failure

Inspection Summary
 The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Inspection report:

Safety is our serious job for our worker and engineer team

