

Inspection Report

Report No.: XYSL-140614
 Supplier : XY-GLOBAL







Inspection Date: 19th Jul, 2014
 Inspector: Leo

Inspection only for: PO . XYSL-140614 Item No. XY11WD038	<u>Inspection Result:</u> PASS
---	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11WD038	18000PCS	5% inspection	0pcs	No failure	18000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

	
<p>1. Packing</p> 	<p>2. Product</p> 
<p>3. Product</p> 	<p>4 Product</p> 
<p>5. Product</p>	<p>6. The test report</p>

名前	OEM
材料	ADC12/A380
表面処理	nickle
公差	+/- 0.01
仕様	OEM
数量	100
納期	25/30
付属品	accessories
規格	Austrial/EU
品質	ISO 9001
保証	1. 10年保証
仕上げ	finishment
種類	kindls
4. 仕様	
5. 仕様	
6. 仕様	
7. 仕様	
8. 仕様	
9. 仕様	
10. 仕様	
11. 仕様	
品質	ISO9001
保証	OEM