

Inspection Report

Report No.: 140321

Inspection Date: 21<sup>st</sup> Mar.2014

Supplier :

Inspector: Ken Tung

Inspection only for:	Inspection Result:
Uniskull, Middle, Spark bolt	PASS

Description	Finished Q'ty(pcs)	Sample Size	Defect Found	Defects Description	Acceptable Q'ty(pcs)
5/8" Uniskull /black	125	100% inspection	0	No failure	125
3/4" Uniskull /black	500	100% inspection	4	Scratch on the surface, the supplier had picked all defects out on-site	500
1" Uniskull /black	125	100% inspection	0	No failure	125
5/8" Uniskull /chrome	125	100% inspection	0	No failure	125
3/4" Uniskull /chrome	125	100% inspection	0	No failure	125
1" Uniskull /chrome	500	100% inspection	0	No failure	500
Middle /black	125	100% inspection	2	Scratch on the surface, the supplier had picked all defects out on-site.	125pcs
Middle /chrome	175	100% inspection	0	No failure	175pcs
Spark bolt /chrome	2000	200	0	No failure	2000



Appearance Inspection :  
No failure

Dimension Inspection:  
No failure

Assembly:  
No failure

Inspection Summary  
For the black Middle and Uniskull, there are scratch on the surface during inspection, but the supplier had picked all rejected products out and reworked all defects in time.

Digital photo records :



品名	铝合金 精密加工零件 OEM 定制
规格	ADC12 A380
材质	铝合金
用途	汽车零部件 精密加工
表面处理	阳极氧化
加工工艺	CNC 精密加工
精度	±0.01mm
MOQ	1000 件
交期	T/T 50% T/T 50%
包装	CNC 加工 铝合金 精密加工
产地	中国 广东 东莞
重量	20-25g
数量	1000 件
1.Name	铝合金 OEM 定制
2.Process	CNC 精密加工
3.	ADC12 A380
4.Surface	阳极氧化/nickle
5.Tolerance	±0.01mm
6.	1000 件
7.Specification	OEM 定制
8.	25-30 天
9.	accessories
10.	Austria EU
11.	ISO 9001
	ISO 9001
	2
	3 surface finishment kinds available
	4
	5
	6
	7
	ISO 9001
	OEM 定制