

□□A380□□□□□□□□□□□□□□□□

Inspection Report

Report No.: XYS-130711
 Supplier : XY-GLOBAL

Inspection Date: 10th Aug, 2013
 Inspector: Leo

Inspection only for: PO . XYS-130711 Item No.XY-3519400	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-3519400	4000PCS	5% inspection	0pcs	No failure	4000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

ชื่อ	บริษัท ออโตเมติก เทคโนโลยี จำกัด OEM
ชื่อ	ADC12 A380
ชื่อ	อะไหล่
ชื่อ	อะไหล่
ชื่อ	CNC
ชื่อ	CNC
ชื่อ	CNC
MOQ	100
ชื่อ/ชื่อ	+/- 0.01mm
ชื่อ	T / T 50%
ชื่อ	CNC
ชื่อ	อะไหล่
ชื่อ	อะไหล่
ชื่อ	20-25 T / T 50%
ชื่อ	อะไหล่
1. ชื่อ OEM 2. ชื่อ CNC 3. Material ADC12 A380 4. ชื่อ 5. ชื่อ ±0.01mm 6. ชื่อ 100 7. ชื่อ OEM service 8. ชื่อ 25-30 9. ชื่อ 10. ชื่อ Austria EU 11. ชื่อ ISO 9001	
1. ISO 10 2. ชื่อ 3. ชื่อ 4. ชื่อ 5. ชื่อ 6. ชื่อ 7. ชื่อ	
ชื่อ ชื่อ ชื่อ ISO 9001 ชื่อ ชื่อ OEM ชื่อ	