

**Inspection Report**

**Report No.:** XYF-130802  
**Supplier :** XY-GLOBAL

**Inspection Date:** 1<sup>th</sup> Sep-, 2013  
**Inspector:** LEO

Inspection only for: PO . XYK-130802      Item No.300-20017	<b>Inspection Result:</b> <b>PASS</b>
--	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
300-20017	10000Set	100% inspection	0pcs	No failure	10000Set

<b>Appearance Inspection :</b> No failure.
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

**Digital photo records :**

	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. inspection reports

