

**Inspection Report**

Report No.: XYN-140608  
 Supplier : XY-GLOBAL

Inspection Date: 2<sup>th</sup> July, 2014  
 Inspector: Leo

Inspection only for: PO . XYN-140608 Item No.135240	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
135240	5000PCS	1% inspection	0pcs	No failure	5000pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

6. Report:

