

Inspection Report

Report No.: XYSK-140617
 Supplier : XY-GLOBAL

Inspection Date: 10th July, 2014
 Inspector: Leo

Inspection only for: PO . XYSK-140617 Item No. XY31SY017	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY017	10000PCS	1% inspection	0pcs	No failure	10000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :																																											
																																											
1. Packing	2. Product																																										
																																											
3. Product	4 Product																																										
	 深圳市真朴电子科技有限公司 XY Electronics Technology Co.,Ltd <table border="1" data-bbox="603 1749 954 2078"> <tr> <td>Client Name</td> <td>XY Electronics Technology Co., Ltd</td> <td>Product Type</td> <td>XY31SY017</td> <td>Inspection Date</td> <td>2014.07.10</td> </tr> <tr> <td>Part No.</td> <td>XY31SY017</td> <td>Lot No.</td> <td>14071001</td> <td>Inspector</td> <td>Leo</td> </tr> <tr> <td>Material</td> <td>Steel</td> <td>Quantity</td> <td>10000</td> <td>Sample Size</td> <td>100</td> </tr> <tr> <td>Inspection Method</td> <td>Visual</td> <td>Inspection Result</td> <td>Pass</td> <td>Defect Count</td> <td>0</td> </tr> <tr> <td>Inspection Standard</td> <td>XY31SY017</td> <td>Inspection Location</td> <td>XY Electronics Technology Co., Ltd</td> <td>Inspection Time</td> <td>10:00 AM</td> </tr> <tr> <td>Inspection Equipment</td> <td>Visual</td> <td>Inspection Environment</td> <td>Normal</td> <td>Inspection Status</td> <td>Completed</td> </tr> <tr> <td>Inspection Operator</td> <td>Leo</td> <td>Inspection Supervisor</td> <td>Leo</td> <td>Inspection Report No.</td> <td>XYSK-140617-01</td> </tr> </table>	Client Name	XY Electronics Technology Co., Ltd	Product Type	XY31SY017	Inspection Date	2014.07.10	Part No.	XY31SY017	Lot No.	14071001	Inspector	Leo	Material	Steel	Quantity	10000	Sample Size	100	Inspection Method	Visual	Inspection Result	Pass	Defect Count	0	Inspection Standard	XY31SY017	Inspection Location	XY Electronics Technology Co., Ltd	Inspection Time	10:00 AM	Inspection Equipment	Visual	Inspection Environment	Normal	Inspection Status	Completed	Inspection Operator	Leo	Inspection Supervisor	Leo	Inspection Report No.	XYSK-140617-01
Client Name	XY Electronics Technology Co., Ltd	Product Type	XY31SY017	Inspection Date	2014.07.10																																						
Part No.	XY31SY017	Lot No.	14071001	Inspector	Leo																																						
Material	Steel	Quantity	10000	Sample Size	100																																						
Inspection Method	Visual	Inspection Result	Pass	Defect Count	0																																						
Inspection Standard	XY31SY017	Inspection Location	XY Electronics Technology Co., Ltd	Inspection Time	10:00 AM																																						
Inspection Equipment	Visual	Inspection Environment	Normal	Inspection Status	Completed																																						
Inspection Operator	Leo	Inspection Supervisor	Leo	Inspection Report No.	XYSK-140617-01																																						
5. Product:	6. report																																										

