

**Inspection Report**







**Report No.:** XYDK-130819  
**Supplier :** XY-GLOBAL

**Inspection Date:**15<sup>th</sup> Sep-, 2013  
**Inspector:**LEO

Inspection only for: PO . XYDK-130819    Item No.400379	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
400379	500PCS	100% inspection	0pcs	No failure	500pcs

<b>Appearance Inspection :</b> No failure.
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

