

**Inspection Report**

Report No.: XYSL-130530  
 Supplier : XY-GLOBAL

Inspection Date: 28<sup>th</sup> Jun, 2013  
 Inspector: Leo

Inspection only for: PO . XYSL-130530 Item No. XY11SL020	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11SL020	22000PCS	5% inspection	0pcs	No failure	22000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. The test report

品名	加工品 加工品 OEM 加工品
品名	品名 ADC12 A380
品名	品名
品名	品名
品名	品名
品名	CNC 加工品 CNC 加工品
品名	品名 gague 加工品 加工品 加工品
MOQ	品名
公差	+/- 0.01
公差	T / T 50 加工品 50 T / T;
公差	CNC 加工品 CNC 加工品 加工品
公差	加工品 加工品 加工品
公差	品名
公差	20-25 T / T 50 加工品
公差	品名
1.Name	品名 OEM 加工品
2.Process	品名 CNC 加工品
3.Material	品名 ADC12 A380
4.Surface	品名 nickle 加工品
5.Tolerance	品名 +/- 0.01
6.	品名 100
7.Specification	品名 OEM service 加工品
8.	品名 25 30
9.	品名 accessorie 加工品
10.	品名 Austrial EU
11.	品名 ISO 9001
品名	
ISO	品名 1. 10
2.	品名
3. surface	品名 finishment kinds available
品名	品名 4.
5.	品名
品名	品名 6.
7.	品名
品名	
品名	加工品 加工品
品名	加工品
品名	品名 ISO9001
品名	加工品
OEM	加工品