

Inspection Report

Report No.: XYAN-150310
 Supplier : XY-GLOBAL

Inspection Date: 16th Apr., 2015
 Inspector: LEO

Inspection only for: PO . XYBA-150310 Item No. XY21ZC097	Inspection Result: PASS
--	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC097	18000pcs	7% inspection	0pcs	No failure	18000pcs

Appearance Inspection :
 No failure,

Dimension Inspection:
 No failure , below measurement report for reference.

Assembly Test:
 No failure

Inspection Summary
 The inspection sample plan is 100% inspection.

Digital photo records :

	
<p>1. Packing</p>	<p>2. Product:</p>
	
<p>3. Product:</p>	<p>4. Product:</p>
	
<p>5. Product :</p>	<p>6. Inspection report:</p>

品名	CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品
材質	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316 POM
仕様	
加工	
公差	CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品
MOQ	
公差	+/- 0.01
納期	T / T 50% T / T
加工	CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品
加工	
加工	20 25 T / T 50
加工	CNC加工品
1.Name	OEM CNC加工品
2.Process	CNC加工品
3.Material	AL6061 AL6065 AL6063 AL7075 POM
4.Surface	nickle
5.Tolerance	+/- 0.01
6.	100
7.Specification	OEM service
8.	25 30
9.	CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品
10.	Austrial EU
11.	ISO 9001
加工	
ISO	1. 10
2.	
3. surface	finishment kinds available
4.	
5.	
6.	
7.	
加工	
CNC	
CNC	
CNC	ISO9001
CNC	
CNC	OEM

Safety is our serious job for our worker and engineer team

