

Inspection Report








Report No.: XYKB-140517
Supplier : XY-GLOBAL

Inspection Date: 12th Jun, 2014
Inspector: Leo

Inspection only for: PO . XYKB-140517 Item No. XY72YM013	Inspection Result: PASS
-------------------------------------------------------------	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY72YM013	5000PCS	1% inspection	0pcs	No failure	5000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	 
5. Product:	6. Dimensions report:

品名	加工品 部品名 部品番号 部品図面参照番号 部品仕様書参照番号 OEM部品名 部品名 部品番号
品名	部品ADC12 A380
品名	部品名
品名	部品名
品名	部品名
品名	CNC 部品名
品名	部品名 gague 部品名
MOQ	部品名
公差	+/- 0.01
公差	T / T 50 部品名 50 T / T; 部品名
公差	CNC 部品名 CNC 部品名
公差	部品名
公差	部品名
公差	20-25 T / T 50 部品名
公差	部品名
1.Name 部品名 OEM 部品名	
2.Process 部品名 CNC 部品名	
3.Material 部品名 ADC12 A380	
4.Surface 部品名 nickel 部品名	
5.Tolerance 部品 +/- 0.01	
6. 部品名 100	
7.Specification 部品 OEM serice 部品名	
8. 部品名 25 30	
9. 部品名 accessoried 部品名	
10. 部品名 Austrial EU	
11. 部品 ISO 9001	
部品名	
ISO 1. 10	
2. 部品名	
3. sureface finishment 部品 kinds available	
部品名 4. 部品名	
5. 部品名	
部品名 6. 部品名	
7. 部品名	
部品名	
部品名	
部品名 ISO9001	
部品名	
OEM 部品名	