

Inspection Report

Report No.: XYK-140530
Supplier : XY-GLOBAL

Inspection Date: 26th Jun, 2014
Inspector: Ken

Inspection only for: PO . XYK-140530 Item No.XY-144320	Inspection Result: PASS
-----------------------------------------------------------	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-144320	80000PCS	1% inspection	0pcs	No failure	80000pcs

Appearance Inspection : No failure.
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

品名	ADC12 A380 CNC加工品 OEM
品番	ADC12 A380
仕様	ADC12 A380
数量	100個
材質	ADC12 A380
加工	CNC加工
公差	±0.01mm
MOQ	100個
納期	受注後50日程度
表面処理	ニッケルメッキ
検査	ISO 9001
1.Name	ADC12 A380 CNC加工品 OEM
2.Process	CNC加工
3.品番	ADC12 A380
4.Surface	ニッケルメッキ
5.Tolerance	±0.01mm
6.数量	100個
7.Specification	OEM
8.納期	25-30日
9.付属品	accessories
10.認証	Austrian EU
11.&NBSP	ISO 9001
ISO	ISO 9001
2.	
3 surface	finishment kinds available
4.	
5.	
6.	
7.	
ISO	ISO 9001
OEM	OEM