

Bahagian CNC

**Inspection Report**

**Report No.:** XYA-130810  
**Supplier :** XY-GLOBAL

**Inspection Date:**11<sup>th</sup> Sep-, 2013  
**Inspector:**LEO

Inspection only for: PO . XYA-130810    Item No.130014	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
130014	<b>5000PCS</b>	3% inspection	0pcs	No failure	5000pcs

<b>Appearance Inspection :</b> No failure.
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :



6. Product: