

Inspection Report

Report No.: 140507-01
Supplier :







Inspection Date: 07th May 2014
Inspector: Ken Tung

Inspection only for: frame sample Item No. XY-Frame-041	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-Frame-041	10sets	100%	0pcs	1pcs poor finish	10pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure
Leakage Test: No failure
Inspection Summary The inspection sample plan are follow AQL . The result of inspection is acceptable.

Digital photo records :

	
1. Product	2. Product
	
3. Product	4. Product
	
5. Product	6. Carton

