

**Inspection Report**

**Report No.:** 140610-01  
**Supplier :**

**Inspection Date:** 10<sup>th</sup> May 2014  
**Inspector:** Ken Tung

Inspection only for: Item No. XY-ARM-07	<b>Inspection Result:</b> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-ARM-07	500sets	100%	0pcs	na	500pcs

**Appearance Inspection :**  
 No failure.

**Dimension Inspection:**  
 No failure, below measurement report for reference.

**Leakage Test:**  
 No failure

**Inspection Summary**  
 The inspection sample plan are follow AQL ,The result of inspection is acceptable.

**Digital photo records :**

	
1. Packing	2. Product
	
3. Product	4. Product
	
5. Product	6. Product
	
7 Packing	8. Carton

